PRINTED: 01/18/2013 FORM APPROVED CENTERS FOR MEDICARE & MEDICAID SERVICES OMB NO. 0938-0391 X2) MULTIPLE CONSTRUCTION STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED 01 . BUILDING 155177 12/13/2012 WING STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 2741 N SALISBURY ST WEST LAFAYETTE, IN 47906 WESTMINSTER VILLAGE - WEST LAFAYETTE (X4) ID SUMMARY STATEMENT OF DEFICIENCIES (X5) (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) PREFIX PREFIX COMPLETION (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG REGULATORY OR LSC IDENTIFYING INFORMATION) TAG DATE K0000 K0000 A Life Safety Code and **Environmental Preoccupancy** Survey for the renovation of the kitchen in area B was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a). Survey Date: 12/13/12 Facility Number: 000093 Provider Number: 155177

AIM Number: NA

Surveyor: Bridget Brown, Medical

Surveyor, Life Safety Code

Specialist

At this Life Safety Code and **Environmental Preoccupancy** survey, Westminster Village-West Lafayette was found in substantial compliance with Requirements for Participation in Medicare/Medicaid 42 CFR Subpart 483.70(a) Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC) Chapter 19, **Existing Health Care Occupancies** and 410 IAC 16.2-3.1-19

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any defiency statement ending with an asterisk (*) denotes a deficency which the institution may be excused from correcting providing it is determined that other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

Facility ID:

PRINTED: 01/18/2013 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE CONSTRUCTION			(X3) DATE SURVEY		
AND PLAN OF CORRECTION IDENTIF		IDENTIFICATION NUMBER:	A. BUILDING 01		01	COMPLETED	
155177		B. WING			12/13/2012		
NAME OF B	AN OLUMBER OR GUIDRU IEI			STREET A	ADDRESS, CITY, STATE, ZIP CODE	•	
NAME OF PROVIDER OR SUPPLIER				2741 N	SALISBURY ST		
WESTMINSTER VILLAGE - WEST LAFAYETTE			WEST LAFAYETTE, IN 47906				
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIES			ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	TE	COMPLETION
TAG				TAG	DEFICIENCE		DATE
	Environmental						
	Standards of th	he Indiana Health					
	Facilities Rules	for Comprehensive					
	care facilities.						
	This one story	facility was					
		be of Type III (211)					
		The facility was fully					
		d has a fire alarm					
	system with hard wired smoke detection in the corridors, resident rooms and spaces open to the						
	corridors. The facility has the						
	capacity for 72 and had a census of 42 residents. All areas where the residents have						
	customary acc	ess were sprinklered					
	and all areas providing facility services were sprinklered. Quality Review by Robert Booher, Life Safety						
	Code Specialist-Me	edical Surveyor on 12/21/12.					
	The Co. 111	. (
	The facility wa						
		mpliance with the					
	aforementione	· ·					
	requirements a	as evidenced by the					
	following:						

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID: VI7Y21

Facility ID: 000093

If continuation sheet Page 2 of 5

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 01/18/2013 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:			(X2) MULTIPLE CO	(X3) DATE SURVEY COMPLETED			
155177		A. BUILDING B. WING	01	12/13/2012			
NAME OF F	PROVIDER OR SUPPLIER			ADDRESS, CITY, STATE, ZIP CODE			
WESTMI	NSTER VILLAGE -	WEST LAFAYETTE	2741 N SALISBURY ST WEST LAFAYETTE, IN 47906				
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIES		ID	PROVIDER'S PLAN OF CORRECTION	(X5)		
PREFIX TAG		H DEFICIENCY MIJST RE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOUL		CROSS-REFERENCED TO THE APPROPRIA	COMPLETION DATE		
	l		I	I .			

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID: VI7Y21

Facility ID: 000093

If continuation sheet Page 3 of 5

PRINTED: 01/18/2013 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER: 155177		A. BUILDING O O O O O O O O O O O O O		(X3) DATE SURVEY COMPLETED 12/13/2012			
		100111	B. WING		12/10/2012		
NAME OF P	ROVIDER OR SUPPLIER	8		ADDRESS, CITY, STATE, ZIP CODE			
WESTMINSTER VILLAGE - WEST LAFAYETTE			2741 N SALISBURY ST WEST LAFAYETTE, IN 47906				
				LALATETTE, IN 47300			
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION	(X5)		
PREFIX TAG				(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	COMPLETION DATE		
K0029	REGULATORY OR LSC IDENTIFYING INFORMATION) NFPA 101			DEFICIENCE)	DATE		
SS=B	LIFE SAFETY CODE STANDARD						
00 5	One hour fire rated construction (with 3/4						
		ors) or an approved					
		tinguishing system in					
		8.4.1 and/or 19.3.5.4 us areas. When the					
	•	atic fire extinguishing					
		used, the areas are					
	separated from other spaces by smoke						
	• .	s and doors. Doors are					
	self-closing and non-rated or field-applied protective plates that do not exceed 48 inches from the bottom of the door are permitted. 19.3.2.1						
	Based on obse	rvation and	K0029	Standard is met under Life Sa	-		
	interview, the f	facility failed to		Code 2012 regulations 18.3.2			
	provide a wall constructed to separate 1 of 1 kitchens in area B from the corridor. LSC requires where hazardous areas are protected by the approved automatic fire extinguishing system, the hazardous area is separated from other spaces by smoke resisting partitions and doors. This deficient practice could affect any occupant in area B where no residents were			1-12. 1)The portion of the hea			
				care facility served by the coof facility is limited to seventee			
				(17) beds. 2) The range is			
				equipped with a range hood o			
				width at least equal to the wid	th		
				of the cooking surface with grease baffles. 3) The hood			
				system has a minimum airflov	v of		
				500 cfm (14,000 L/min.). 4) TI			
				hood system is ducted to the			
				exterior. 5) The range complied			
				with all of the following: a) The range is protected with a fire	IC		
				suppression system listed in			
		idents were		accordance with UL 300. b) A		
	housed.			manual release of the	11		
	Findings include:			extinguishing system is provide in accordance with NFPA 96.			
	i maniga melue	munigs include.		An interlock is provided to turn	n off		
	Rasad on obse	rvation with the		gas to the range when the	tod		
				suppression system is activated. 8) No solid fuel is used for	ıcu.		
	maintenance director and administrator on 12/13/12 at			cooking. 7) No deep-fat frying			
				equipment is present. 8) Porta			

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID: VI7Y21

Facility ID: 000093

If continuation sheet

Page 4 of 5

PRINTED: 01/18/2013 FORM APPROVED OMB NO. 0938-0391

	IT OF DEFICIENCIES OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155177	(X2) MULTIPLE CO A. BUILDING B. WING	ONSTRUCTION 01	(X3) DATE COMPL 12/13/	ETED	
NAME OF PROVIDER OR SUPPLIER WESTMINSTER VILLAGE - WEST LAFAYETTE			STREET ADDRESS, CITY, STATE, ZIP CODE 2741 N SALISBURY ST WEST LAFAYETTE, IN 47906				
(X4) ID PREFIX TAG	(EACH DEFICIEN	TATEMENT OF DEFICIENCIES ICY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE API DEFICIENCY)	ULD BE PROPRIATE	(X5) COMPLETION DATE	
	in area B was corridor. There separate the control the exit corridor administrator and so	acknowledged the aid the construction a for kitchens under		fire extinguishers in account NFPA 96 are located kitchen areas. 9) A switch meeting all of the following provided: a) A locked suprovided within the cook that deactivates the range whenever the not under staff supervision of the range whenever the not under staff supervision. The switch is on a timer, exceeding a 120-minute that automatically deact the range, independent action. 10) Procedures for inspection, testing, and maintenance of the cook equipment are in accord Chapter 11 of NFPA 96 manufacturer's instructionare followed. 11) Heat sellocated in the cooking all kitchen. 12) No smoke delocated less than 20 feer range.	ed in all eth ng is witch is ing facility nge. b) activate kitchen is sion. c) not capacity, etivates of staff or use, king lance with and the ons and ensors are rea of the etector is		

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID: VI7Y21

Facility ID: 000093

If continuation sheet

Page 5 of 5